

Attachment E

Summary of Distribution Circuit Field Inspection by ICC Staff			
Utility:	IP	Date:	5/28/02
Circuit:	Hillsboro 855 (Carlinville)	Inspector:	J. D. Spencer, Bev Hall (IP)
Gen. Notes: Many animal guards have been installed on this circuit.			
Map No.	Item Description	Photo(s)	Location
1 of 2	Broken strands in neutral conductor		2nd span north of Sta. 21813 on Rd. 1375E
1	Woodpecker hole in pole		1st pole south of Breckenridge St. on Rd. 1375E
2	NESC violation: Downguy with inadequate height of strain insulator (less than 8 ft. above ground when DG broken)		Corner of West & Jackson Sts.
2	Shell rotted pole	B12, B13	At Sta. 15437 on Jackson St. west of High St.
2	Pole rotted at ground line & bad end of crossarm		At Sta. 10443 on Maple St. west of Johnson St.
2	Bad pole top		1st pole south of Beaver St. in alley between Charles & High Sts.